

Instruction Manual For Bsa Models B31 350 Cc Ohv B32 350 Cc Ohv Competition B32 350 Cc Ohv Gold Star B33 500 Cc Ohv B34 500 Cc Ohv Competition And B34 500 Cc Ohv Gold Star

172 pgs, more than 240 illustrations and charts, size 8.25 x 10.75". In 1945, after the war had ended, BSA resumed production of their civilian line of motorcycles. However, they continued their pre-war practice of publishing repair, overhaul and technical information in the form of individual 'Service Sheets'. These sheets were 'dealer only' publications and, as such, the print quality was somewhat questionable. It was not until the early 60's that BSA eventually started publishing model specific workshop manuals that were available to the general public. Consequently, these 'Service Sheets' were the only publications available for the maintenance and repair of BSA models from 1945 through the mid 60's. At some point in the 1930's, BSA began identifying their various model types by 'groups' and the models manufactured from 1945 through the mid 60's were in Groups A, B, C, D and M. The service sheets were identified numerically and while there are some exceptions, the numbers relate to a particular model group. They are as follows: The 200 series of service sheets were applicable to Group A models, the 300 series to Group B, the 400 series to Group C, the 500 series to Group D and the 600 series to Group M. Also, there was a 700 series applicable to mechanical maintenance and an 800 series for electronic service and wiring diagrams. Both the 700 and 800 series of service sheets contained information that was not model specific but was applicable across multiple model groups. Unfortunately, as these service sheets were issued individually and at random times, the numbering sequence within a group is, at times, illogical and not necessarily consecutive. Consequently, assembling those individual sheets into a publication that serves as a model specific workshop manual is a somewhat difficult task and owners of BSA motorcycles are subjected to considerable confusion surrounding the appropriate selection from the multitude of reprints that have recently flooded the on-line marketplace. Many of the reprints found on internet websites are from 'bedroom sellers' at enticingly low prices by individuals that really have no idea what they are selling. Many are nothing more than poor quality comb-bound photocopies that are scanned and printed complete with greasy pages and thumbprints and are deceptively described as 'pre-owned', 'used' or even 'refurbished'! In addition, they are often advertised for the incorrect series and/or model years of motorcycles. The most complete compilation of the 1945 and onwards service sheets was a BSA 'dealer only' ring binder that contained all of the individual service sheets totaling to almost 500 pages. This manual contains 51 service sheets(169 pgs) and includes 14 sheets(62 pgs) from that 'dealer only' publication plus the 37 service sheets(107 pgs) that were published by BSA under part number 00-4021. It covers the S.V. and O.H.V. rigid, spring frame, girder and telescoping fork M20, M21 and M33 models from 1945-63. Obviously, as the M20 and M21 were introduced in 1937, this manual will also be of use to owners of those earlier models. Please note that service sheets other than those in the 600 series that are included in this publication may also contain data that is applicable to 'other' model groups, as that was the original intention. For additional information the reader is directed to 'The Book of the BSA 250cc,350cc,500cc & 600cc OHV&SV singles 1945-1959' (ISBN 9781588502292) which covers the B31, B32, B33, B34, C10, C11, C11DL, M20, M21 & M33 models. The OHV 1955-1958 M33 models are also covered in 'The Book of the BSA OHV Singles 350cc & 500cc 1955-1967' (ISBN 9781588501561)

184 pages, and more than 120 illustrations and charts, size 8.25x10.75 inches. This manual is a compilation of three factory publications including the owner's instruction manual, the parts/spares manual and a set of service sheets. These publications cover all three variations of the 175cc two-stroke and the 250cc four-stroke and electric start models manufactured from 1959-1965. Neither BSA nor Triumph ever published a workshop manual for these models, however, the combination of these three publications provides the most comprehensive maintenance and repair information that was ever made available from the manufacturer. MANUALS & TECHNICAL PUBLICATIONS: Maintenance, repair and service information was issued under both the BSA and Triumph name. However, as the machines were identical in all aspects, any technical documentation can be applied to either manufacturer without hesitation. SERVICE SHEETS: Beginning in December 1959, both BSA and Triumph began publishing repair, overhaul and technical information in the form of individual (dealer only) 'Service Sheets'. It should be noted that it was never intended that these service sheets would be distributed to the general public. However, they were eventually combined into a

single publication and released under both the BSA and Triumph names, the contents being identical in either case. INSTRUCTION MANUAL: Both BSA and Triumph published an identical 'Instruction Manual' the only difference being the name on the front cover. These publications were somewhat more detailed than typical 'owner's manuals' as they included overhaul information in addition to general maintenance and adjustments. As these instruction manuals were included with each new scooter purchased, there were a number of 'editions' published during the lifetime of the model, however, the contents remained basically unchanged. When combined with the 'Service Sheets' they are a reasonable substitute for a workshop manual. PARTS (or) SPARES MANUAL: The parts manuals are also identical and include exploded component diagrams that are extremely helpful in the rebuilding or restoration process. ADDITIONAL DATA: There is an addendum to the rear of this manual that contains a number of communications that were sent from the UK factory to their US distributors. These documents are somewhat rare and they may be of help in assisting in the maintenance of one of these machines. DESIGN & GENERAL SPECIFICATIONS: Designed by Edward Turner (Triumph) and sold under both BSA and Triumph brand names to take advantage of established distribution networks, this badge engineering was one of the last uses of the Sunbeam name. The differences between the BSA Sunbeam and Triumph Tigress were entirely cosmetic—the former in polychromatic green paint, also two-tone red and cream, with a BSA badge; the latter in a shell blue or mimosa and ivory (two-tone) with a Triumph badge. Introduced in late 1959, the scooter was available with a 250 cc four-stroke twin (10hp), or 175cc two-stroke single cylinder engine (7.5hp). Both engines were forced-air-cooled. The two-stroke was a development of the BSA Bantam engine but the four-stroke was a completely new parallel-twin with a gear drive to the gearbox. The contact-breaker fed two separate ignition coils, each of which connected directly to its own spark plug without the need for a distributor. Drive to the rear wheel was by a fully enclosed chain in an oil bath. Both versions had four, foot-operated gears. Some of the 250 twins were fitted with an electric starter and a 12 volt (not 6 volt) electrical system, they were identified as either B2S (Sunbeam) or TW2S (Triumph). The 250 cc four-stroke model was discontinued in 1964 and the 175cc two-stroke model in 1965.

How to Restore Triumph Trident T150/T160 & BSA Rocket III

Motor-cycling for Women 1928

The BSA Bantam Bible

Original 1911 Edition

WALNECK'S CLASSIC CYCLE TRADER, ISSUE #33

Service, Repair, Maintenance

Takes the BSA (and Triumph) Unit Single engine apart, and then shows how to rebuild the engine. This book includes wiring diagrams, complete specifications, hundreds of illustrations, and, advice and tuning tips. It is of interest to BSA enthusiasts since it charts the development of one of the most successful machines to come out of Small Heath.

Completed at home by an enthusiastic DIY mechanic who has great experience rebuilding bikes, this book covers the complete restoration of a Triumph Trident T150V and a Triumph T160. Each and every aspect of the dismantling, refurbishment and reassembly of these classic bikes is covered in great detail, accompanied by a host of clear colour photos.

'58-'72

B. S. A. Singles Restoration

BSA Dandy 1957-1962 Workshop Manual

WALNECK'S CLASSIC CYCLE TRADER, NOVEMBER 1988

BSA BANTAM D1-D3-D5-D7 'SERVICE SHEETS' 1948-1966 RIGID, SPRING FRAME AND SWING ARM 125cc-150cc-175cc MODELS

The Book of the BSA - An Owners Workshop Manual for Pre-War BSA Motorcycles

94 pages, 54 illustrations, size 5.5 x 8.5 inches. An illustrated Owner's Workshop Manual covering Pre-War BSA Single and Twin-Cylinder SV and OHV Motorcycles. This is a faithful reproduction of the Floyd Clymer (W.C. Haycraft) Book Of The BSA originally published in the US in 1947. Much more detailed than the owner's handbook, this manual includes complete technical data, service and maintenance information and detailed instructions for the repair and overhaul of the major mechanical and electrical components for the majority of the pre-war BSA single and twin cylinder motorcycles. However, as this manual was written specifically for the motorcycles constructed between 1936 through 1939 the information may not be quite as comprehensive for the earlier versions of these models. There is adequate detailed text and diagrams to assist in major refurbishing such as an engine rebuild or even a complete mechanical renovation, making it an invaluable resource for collectors and restorers of these classic BSA motorcycles. OHV and SV Models covered by this publication are: 150c.c. - X0. 250c.c. - B1, B2, B18, B20, B21, B22, C10, C11. 350c.c. - B23, B24, B25, B26, M19, R4, R5, R17, R19, R20. 500c.c. - J12, M20, M22, M23, M24, Q7, Q8, Q21, W6.

600c.c. - M10, M21. 750c.c. - Y13. 1,000c.c. - G14.

110 pages, and 70 illustrations and charts, size 5.5x8.5 inches. This publication covers all three variations of the BSA Sunbeam and Triumph Tigress 175cc two-stroke and the 250cc four-stroke and electric start models manufactured from 1959 to 1965. Originally published under the same title in 1967 as a corrected version of the previous 1963 edition by J. Thorpe, this book is one of The Motorcyclist's Library series published in the USA by Floyd Clymer by arrangement with the original publishers, Pitman Ltd. of London, England. **MANUALS & TECHNICAL PUBLICATIONS:** Neither BSA nor Triumph ever published a workshop manual for these models, however, those owners interested in acquiring additional technical information are directed to our publication ISBN 9781588502537 which includes a compilation of the 3 major factory manuals identified below. The combination of these three publications provides the most comprehensive maintenance and repair information that was ever made available from the manufacturer. Maintenance, repair and service information was issued under both the BSA and Triumph name. However, as the machines were identical in all aspects, any technical documentation can be applied to either manufacturer without hesitation. **SERVICE SHEETS:** Beginning in December 1959, both BSA and Triumph began publishing repair, overhaul and technical information in the form of individual (dealer only) 'Service Sheets'. It should be noted that it was never intended that these service sheets would be distributed to the general public. However, they were eventually combined into a single publication and released under both the BSA and Triumph names, the contents being identical in either case. **INSTRUCTION MANUAL:** Both BSA and Triumph published an identical 'Instruction Manual' the only difference being the name on the front cover. These publications were somewhat more detailed than typical 'owner's manuals' as they included overhaul information in addition to general maintenance and adjustments. As these instruction manuals were included with each new scooter purchased, there were a number of 'editions' published during the lifetime of the model, however, the contents remained basically unchanged. When combined with the 'Service Sheets' they are a reasonable substitute for a workshop manual. **PARTS (or) SPARES MANUAL:** The parts manuals are also identical and include exploded component diagrams that are extremely helpful in the rebuilding or restoration process. **DESIGN & GENERAL SPECIFICATIONS:** Designed by Edward Turner (Triumph) and sold under both BSA and Triumph brand names to take advantage of established distribution networks, this badge engineering was one of the last uses of the Sunbeam name. The differences between the BSA Sunbeam and Triumph Tigress were entirely cosmetic - the former in polychromatic green paint, also two-tone red and cream, with a BSA badge; the latter in a shell blue or mimosa and ivory (two-tone) with a Triumph badge. Introduced in late 1959, the scooter was available with a 250cc four-stroke twin (10 hp), or 175 cc two-stroke single cylinder engine (7.5 hp). Both engines were forced-air-cooled. The two-stroke was a development of the BSA Bantam engine but the four-stroke was a completely new parallel-twin with a gear drive to the gearbox. The contact-breaker fed two separate ignition coils, each of which connected directly to its own spark plug without the need for a distributor. Drive to the rear wheel was by a fully enclosed chain in an oil bath. Both versions had four, foot-operated gears. Some of the 250 twins were fitted with an electric starter and a 12 volt (not 6 volt) electrical system, they were identified as either B2S (Sunbeam) or TW2S (Triumph). The 250cc four-stroke model was discontinued in 1964 and the 175cc two-stroke model in 1965.

BSA Unit Singles Owners Workshop Manual, No. 127

Boy Scouts Handbook

Handbook for Scout Masters

The Development History of the Gold Star BSA

WALNECK'S CLASSIC CYCLE TRADER, ISSUE #32

B.S.A. Model D10 Instruction Manual, -1967

196 pages, and more than 250 illustrations and charts, size 8.25 x 10.75 inches. In 1945, after the war had ended, BSA resumed production of their civilian line of motorcycles. However, they continued their pre-war practice of publishing repair, overhaul and technical information in the form of individual 'Service Sheets'. These sheets were 'dealer only' publications and, as such, the print quality was at times somewhat questionable. It was not until the early 1960's that BSA eventually started publishing model specific workshop manuals that were available to the general public. Consequently, these 'Service Sheets' were the only publications available for the maintenance and repair of BSA models that were manufactured through the early 1960's. At some point in the 1930's, BSA adopted the practice of identifying their various model types by 'groups' and the models manufactured from 1945 through the early 1960's were in Groups A, B, C, D and M. The service sheets that were associated to a particular group were identified numerically and, while there were some exceptions due to overlapping data between models, in general terms the numbers relate to a particular model group. They are as follows: The 200 series of service sheets were applicable to Group A models, the 300 series to Group B, the 400 series to Group C, the 500 series to Group D and the 600 series to Group M. In addition, there were a 700 series applicable to mechanical maintenance and an 800 series for electronic service and wiring diagrams. Both the 700 and 800 series of service sheets contained information that was not model specific but was applicable across multiple model groups. Unfortunately, as these service sheets were issued individually and at random times, the numbering sequence within any group is not necessarily consecutive and, at times, illogical. Consequently, assembling those individual sheets into a publication that serves as a model specific workshop manual is a somewhat difficult task and owners of BSA motorcycles are subjected to considerable confusion surrounding the appropriate selection from the multitude of reprints that have recently flooded the on-line marketplace. Many of the reprints found on internet websites are from 'bedroom sellers' at enticingly low prices by individuals that really have no idea what they are selling. Many are nothing more than poor quality comb-bound photocopies that are scanned and printed complete with greasy pages and thumbprints and, as such, are deceptively described as 'pre-owned', 'used' or even 'refurbished'! In addition, they are often advertised for the incorrect series and/or model years of motorcycles. The most complete compilation of the 1945 and onwards service sheets was issued by BSA in the form of a 'dealer only' ring binder that contained all of the individual service sheets totaling to almost 500 pages. This manual is a compilation of the service sheets that were collated and published by BSA in the late 1950's and early 1960's under part numbers 00-4017 (pre-swing arm) and 00-4047 (swing arm), which excluding duplicates, consisted of 44 service sheets in total. However, an additional 14 sheets from the ring bound 'dealer only' publication have been added to produce a single manual containing 58 service sheets (190 pages) that cover the entire range of pre-unit A7 and A10 models from 1947 to 1962. Please note that service sheets in the 300, 700 and 800 series that are included in this publication will also include data that is applicable to 'other' model groups, as that was the original intention. For additional information the reader is directed to 'The Book of the BSA Twins 650cc & 500cc 1948-1962' (ISBN 9781588500977).

The BSA range of unit construction singles was in production for fifteen years, and spanned the time of BSA's greatest success, to the eventual failure of the company. In that time, the range provided BSA with their basic

'bread and butter' machines, gave thousands of learners an introduction to motorcycling, provided BSA with many national and world championship wins in the off road arena, mobilized the British Army and gave trail riders the world over the means to further their hobby. This illustrated history of the BSA unit singles runs from the 250cc ohv single cylinder C15 Star of 1958 to the B50 of 1971 and includes all the Triumph-badge derivatives. Matthew Vale provides not only the history but much practical advice relating to the purchase, restoration and maintenance of these machines.

The Complete Story including the Triumph Derivatives

Instruction Manual BSA C10/11/12 250/350cc 1938-53

The Rupert Ratio Unit Single Engine Manual for BSA C15 B25 B40 B44 B50

Goldie

Federal Reserve Manual

'47-'62

222 pages, and more than 250 illustrations and charts, size 8.25 x 10.75 inches. In 1945, after the war had ended, BSA resumed production of their civilian line of motorcycles. However, they continued publishing repair, overhaul and technical information in the form of individual 'Service Sheets'. These sheets were 'dealer only' publications and, as such, the print quality was at times somewhat questionable. It was not until the early 1960's that BSA eventually started publishing model specific workshop manuals that were available to the general public. Consequently, these 'Service Sheets' were the only publications available for the maintenance and repair of BSA models that were manufactured through the early 1960's. At some point in the 1930's, BSA adopted the practice of identifying their various model types by 'groups' and the models manufactured from 1945 through the mid 1960's were in Groups A, B, C, D and M. The service sheets that were associated to a particular group were identified numerically and, while there were some exceptions due to overlapping data between models, in general terms the numbers relate to a particular model group. They are as follows: The 200 series of service sheets were applicable to Group A models, the 300 series to Group B, the 400 series to Group C, the 500 series to Group D and the 600 series to Group M. In addition, there were a 700 series applicable to mechanical maintenance and an 800 series for electronic service and wiring diagrams. Both the 700 and 800 series contained information that was not model specific but was applicable across multiple model groups. Unfortunately, as these service sheets were issued individually and at random times, the numbering sequence within any group is, at times, illogical and not necessarily consecutive. Consequently, assembling those individual sheets into a publication that serves as a model specific workshop manual is a somewhat difficult task and owners of BSA motorcycles are subjected to considerable confusion surrounding the appropriate selection from the multitude of reprints that have recently flooded the on-line marketplace. Many of the reprints found on internet websites are from 'bedroom sellers' at enticingly low prices by individuals that really have no idea what they are selling. Many are nothing more than poor quality comb-bound photocopies that are scanned and printed with large margins, bleed-through and thumbprints and, as such, are deceptively described as 'pre-owned', 'used' or even 'refurbished'! In addition, they are often advertised for the incorrect series and/or model years of motorcycle. A compilation of the 1945 and onwards service sheets was issued by BSA in the form of a 'dealer only' ring binder that contained all of the individual service sheets totaling to almost 500 pages, it is available to find. This manual contains 63 service sheets (210 pages) extracted from that 'dealer only' publication, which cover the pre-unit 1945 to 1958 rigid and spring frame C10, C10L, C11, C11G and the C15. Obviously, as the C10 was introduced in 1938 this manual will also be of use to owners of those earlier models. Please note that service sheets other than those in the 400 series that are included contain data that is applicable to 'other' model groups, as that was the original intention. For additional information the reader is directed to 'The Book of the BSA 250cc, 350cc, 500cc & 600cc' (ISBN 9781588502292) which covers the B31, B32, B33, B34, C10, C11, C11DL, M20, M21 & M33 models.

Year-by-year evolution of the BSA Bantam, a simple commuter bike that thousands learnt to ride on. It became the standard GPO 'telegram bike' in the 1950s and was a huge success, with 100,000 production. It's a story with interesting asides, like the Hummer, Harley-Davidson's version of the DKW that inspired the Bantam, and survived into the 1960s. But it's a sad story too - BSA failed to continue its success by developing it, and by the mid-1960s it was looking outdated, especially next to the new breed of four-stroke Hondas. That the Bantam was allowed to fizzle out in 1971 symbolised the end of an era, but today there's a thriving community of Bantam owner/riders. The book ends with a guide to buying a secondhand Bantam, along with useful appendices on specifications, engine/frame numbers, clubs and Bantam specialists. Every Bantam owner, or would be owner, needs this book - the Bantam Bible!

BSA Instruction Manual

WALNECK'S CLASSIC CYCLE TRADER, MARCH 1988

BSA Sunbeam & Triumph Tigress Scooter 1959-1965 Workshop Manual

Models B31 350 C.c. O.H.V ...

Clymer Vintage British Street Bikes: BSA, Norton, Triumph Repair Manual

BSA Bantam Owners Workshop Manual

194 pages, and more than 240 illustrations and charts, size 8.25 x 10.75 inches. In 1945, after the war had ended, BSA resumed production of their civilian line of motorcycles. However, they continued their pre-war practice of publishing repair, overhaul and technical information in the form of individual 'Service Sheets'. These sheets were 'dealer only' publications and, as such, the print quality was at times somewhat questionable. It was not until the early 1960's that BSA eventually started publishing model specific workshop manuals that were available to the general public. Consequently, these 'Service Sheets' were the only publications available for the maintenance and repair of BSA models that were manufactured through the early 1960's. At some point in the 1930's, BSA adopted the practice of identifying their various model types by 'groups' and the models manufactured from 1945 through the mid 1960's were in Groups A, B, C, D and M. The service sheets that were associated to a particular group were identified numerically and, while there were some exceptions due to overlapping data between models, in general terms the numbers relate to a particular model group. They are as follows: The 200 series of service sheets were applicable to Group A models, the 300 series to Group B, the 400 series to Group C, the 500 series to Group D and the 600 series to Group M. In addition, there were a 700 series applicable to mechanical maintenance and an 800 series for electronic service and wiring diagrams. Both the 700 and 800 series of service sheets contained information that was not model specific but was applicable across multiple model groups. Unfortunately, as these service sheets were issued individually and at random times, the numbering sequence within any group is, at times, illogical and not necessarily consecutive. Consequently, assembling those individual sheets into a publication that serves as a model specific workshop manual is a somewhat difficult task and owners of BSA motorcycles are subjected to considerable confusion surrounding the appropriate selection from the multitude of reprints that have recently flooded the on-line marketplace. Many of the reprints found on internet websites are from 'bedroom

sellers' at enticingly low prices by individuals that really have no idea what they are selling. Many are nothing more than poor quality comb-bound photocopies that are scanned and printed complete with greasy pages and thumbprints and, as such, are deceptively described as 'pre-owned', 'used' or even 'refurbished'! In addition, they are often advertised for the incorrect series and/or model years of motorcycles. The most complete compilation of the 1945 and onwards service sheets was issued by BSA in the form of a 'dealer only' ring binder that contained all of the individual service sheets totaling to almost 500 pages, it is extremely scarce and difficult to find. This manual contains 59 service sheets (190 pages) extracted from that 'dealer only' publication, which cover the 1945 to 1960 pre-unit, rigid, plunger and swing arm B31, B32, B33 and B34 plus Gold Star and Competition models. Please note that service sheets other than those in the 300 series that are included in this publication may also contain data that is applicable to 'other' model groups, as that was the original intention. For additional information the reader is directed to 'The Book of the BSA 250cc, 350cc, 500cc & 600cc OHV & SV singles 1945 to 1959' (ISBN 9781588502292) which covers the B31, B32, B33, B34, C10, C11, C11DL, M20, M21 & M33 models. For later models see 'The Book of the BSA OHV Singles 350cc & 500cc 1955-1967' (ISBN 9781588501561) which covers the B31, B32, B33, B34 & Star B40 & SS90.

A reprint of the first Boy Scouts handbook from 1911 covers woodcraft, camping, signs and signaling, first aid, chivalry, and games.

BSA A7/A10 Owners Workshop Manual

Instruction Manual For Bsa Models C15, C15t, C15s, B40

Mercian Motorcycle Manuals

WALNECK'S CLASSIC CYCLE TRADER, FEBRUARY 1988

123cc 148cc 174cc 1948-1971

BOOK OF THE BSA SUNBEAM & TRIUMPH TIGRESS 175cc & 250cc SCOOTERS 1959 TO 1965

Haynes offers the best coverage for cars, trucks, vans, SUVs and motorcycles on the market today. Each manual contains easy to follow step-by-step instructions linked to hundreds of photographs and illustrations. Included in every manual: troubleshooting section to help identify specific problems; tips that give valuable short cuts to make the job easier and eliminate the need for special tools; notes, cautions and warnings for the home mechanic; color spark plug diagnosis and an easy to use index.

106 pages, and more than 75 illustrations and charts, size 8.25 x 10.75 inches. This manual is a compilation of three factory publications including the 'How to ride the BSA Dandy' instruction manual, the parts/spares manual and a compilation of specific 'dealer only' service sheets. It should be noted that BSA never published a workshop manual for the Dandy, however, the combination of these three factory publications provides the most comprehensive maintenance and repair information that was ever made available from the manufacturer. MANUALS & TECHNICAL PUBLICATIONS: SERVICE SHEETS: In 1945, after the war had ended, BSA resumed production of their civilian line of motorcycles.

However, they continued their pre-war practice of publishing repair, overhaul and technical information in the form of individual 'Service Sheets'. It should be noted that BSA never intended that these service sheets would be distributed to the general public they were 'dealer only' publications. Consequently, these 'Service Sheets' were the only publications available for the maintenance and repair of BSA models that were manufactured through the early 1960's. INSTRUCTION MANUAL: BSA published an 'Instruction Manual' titled, 'How to ride the BSA Dandy'. This publication was somewhat more detailed than most typical 'owner's manuals' as it included basic overhaul information in addition to general maintenance and adjustments. However, when used in conjunction with the 'Service Sheets' they are a reasonable substitute for a workshop manual. PARTS (or) SPARES MANUAL:

The parts manual includes exploded component diagrams which are extremely helpful in the rebuilding or restoration process. MEET THE PUBLISHER VelocePress.com has been publishing reprints of motorcycle and automobile manuals since 2003 and our publications have earned excellent reviews worldwide so you can be assured you are purchasing a quality product. We encourage you to exercise caution when purchasing a manual for your motorcycle as many of the reprints found on internet websites are from 'bedroom sellers' at enticingly low prices by individuals that really have no idea what they are selling. Many are nothing more than poor quality comb-bound photocopies that are scanned and printed complete with greasy pages and thumbprints and, as such, are deceptively described as 'pre-owned', 'used' or even 'refurbished'! In addition, they are often advertised for the incorrect series and/or model years. With more than 250 titles in print VelocePress is one of the fastest growing specialty automobile and motorcycle publishing companies in the USA. Please visit our website at www.VelocePress.com for more information on our company and our books.

Instruction Manual for BSA

Maintenance Manual and Instruction Book for Motorcycle Bsa M20

BSA M20, M21 and M33 'Service Sheets' 1945-1963 for All Rigid, Spring Frame, Girder and Telescopic Fork Models

WALNECK'S CLASSIC CYCLE TRADER, JANUARY 1988

WALNECK'S CLASSIC CYCLE TRADER, OCTOBER 1985

162 pages, and more than 200 illustrations and charts, size 8.25 x 10.75 inches. In 1945, after the war had ended, BSA resumed production of their civilian line of motorcycles. However, they continued their pre-war practice of publishing repair, overhaul and technical information in the form of individual 'Service Sheets'. These sheets were 'dealer only' publications and, as such, the print quality was at times somewhat questionable. It was not until the early 1960's that BSA eventually started publishing model specific workshop manuals that were available to the general public.

Consequently, these 'Service Sheets' were the only publications available for the maintenance and repair of BSA models that were manufactured through the early 1960's. At some point in the 1930's, BSA adopted the practice of identifying their various model types by 'groups' and the models manufactured from 1945 through the mid 1960's were in Groups A, B, C, D and M. The service sheets that were associated to a particular group were identified numerically and, while there were some exceptions due to overlapping data between models, in general terms the numbers relate to a particular model group. They are as follows: The 200 series of service sheets were applicable to Group A models, the 300 series to Group B, the 400 series to Group C, the 500 series to Group D and the 600 series to Group M. In addition, there were a 700 series applicable to mechanical maintenance and an 800 series for electronic service and wiring diagrams. Both the 700 and 800 series of service sheets contained information that was not model specific but was applicable across multiple model groups. Unfortunately, as these service sheets were issued individually and at random times, the numbering sequence within any group is, at times, illogical and not necessarily consecutive. Consequently, assembling those individual sheets into a publication that serves as a model specific workshop manual is a somewhat difficult task and owners of BSA motor cycles are subjected to considerable confusion surrounding the appropriate selection from the multitude of reprints that have recently flooded the on-line marketplace. Many of the reprints found on internet websites are from 'bedroom sellers' at enticingly low prices by individuals that really have no idea what they are selling. Many are nothing more than poor quality comb-bound photocopies that are scanned and printed complete with greasy pages and thumbprints and, as such, are deceptively described as 'pre-owned', 'used' or even 'refurbished'! In addition, they are often advertised for the incorrect series and/or model years of motorcycles. The most complete compilation of the 1945 and onwards service sheets was issued by BSA in the form of a 'dealer only' ring binder that contained all of the individual service sheets totaling to almost 500 pages, it is extremely scarce and difficult to find. This manual includes the 27 service sheets (84 pages) published by BSA under part number 00-4020. However, an additional 15 service sheets have been added from that 'dealer only' publication, to produce a single manual containing 42 service sheets (150 pages) that cover the 1948 to 1966 rigid, spring frame, swing arm D1, D3, D5 and D7 Bantam. Obviously, as the 1966 D10 and the 1968 to 1970 D14 models share many mechanical similarities with the D7, this manual will also be of use to owners of those later models. Please note that service sheets other than those in the 500 series that are included in this publication may also contain data that is applicable to 'other' model groups, as that was the original intention. For additional information the reader is directed to 'The Book of the BSA Bantam' (ISBN 9781588502100) which covers all Bantam models from 1948 to 1971.

Complete Factory Handbook for the BSA Model B20 500 c.c.

Models 1946-1955

BSA C10-C10I-C11-C11g-C12 'Service Sheets' 1945-1958 for All Pre-Unit S.V. and O.H.V. Rigid, Spring Frame and Swing Arm Models

Instruction Manual for BSA Models C15, C15T, C15S, C15 SS80, B40, B40SS90

BSA Unit Singles

A Book for the Lady Driver, Sidecar Passenger and Pillion Rider

BSA B31 - B32 - B33 - B34 'Service Sheets' 1945-1960 for All Pre-Unit Rigid, Spring Frame and Swing Arm Models

Betty and Nancy Debenham were a pair of young adventurous lady motorcyclists who entered trials competitions on equal terms with men in the 1920's. Although the motorcyclists they never let this get in the way of their tremendous sense of fun. Their spirit shines through in 'Motor Cycling for Women'. A practical and yet at times a book from a by-gone era that will make you smile.

Instruction Manual For Bsa Models C15, C15t, C15s, B40BSA Instruction ManualModels 1946-1955Instruction Manual for BSA Models C15, C15T, C15S, C15 SS80, B40 B40SS90Instruction Manual for BSAModels B31 350 C.c. O.H.V ...BSA Dandy 1957-1962 Workshop ManualVeloce Enterprises, Incorporated

Boy Scouts of America

YOUR step-by-step colour illustrated guide to complete restoration

Maintenance Manual and Instruction Book for Motor Cycle (solo) 500 C.c. S.V. BSA Model M20

BSA A7 - A10 'Service Sheets' 1947-1962 for All Rigid, Spring Frame and Swing Arm Group 'a' Motorcycles

BSA A7 and A10 Twins Owners Workshop Manual, No. 121

All Models 1948 to 1971

Haynes disassembles every subject vehicle and documents every step with thorough instructions and clear photos. Haynes repair manuals are used by the pros, but written for the do-it-yourselfer.